FOR USE WITH STARTER SIZE "2" — BULLETINS A10, B10 & A50

HEATER COIL SELECTION

This overload relay has two steps of adjustment (low or high) obtained by positioning the heater coils as shown in the Heater Coil Selection Table. Note the location of the pointed terminal on the heater coil.

Select heater coils according to the motor ampere rating. Note both the catalog number and the position in which the coils must be mounted. Mount the coils in the position corresponding to the column that includes the motor ampere rating. All coils must be mounted in the same position for a given overload relay.

position for a given overload relay.

The Heater Coil Selection Table is for use with motors having a 1.15 service factor. The selected heater coils will allow a maximum of 125% of rated motor current. For motors with a 1.0 service factor use one size smaller heater coil mounted in the same position as the regular larger

The approximate ultimate tripping current, in a 40° C ambient, can be determined by multiplying the minimum currents by 1.25.

| | HEA | TER COIL S | ELECTION T | ABLE | |
|--|--|------------------------------|--|---|--------------------------------------|
| MOTOR AMPERE RATING | | | Low Min. May | High | No. on Coil |
| Heater Co | High | | Min Max 10.9-11.4 12.1-12.7 13.5-14.2 15.0-15.8 17.7-18.6 | 11.5–12.0 12.8–13.4 14.3–14.9 15.9–17.6 18.7–19.0 | 1037 1038 1039 1040 1041 |
| Min Max 3,72–3.93 | Min Max 3.94-4.10 | No. on Coil | 19.1–20.2 21.6–22.8 24.6–26.0 28.0–29.6 32.1–33.9 | 20.3–21.5 22.9–24.5 26.1–27.9 29.7–32.0 34.0–36.6 | 1042 1043 1044 1045 1046 |
| 4.11–4.35 4.60–4.87 5.08–5.37 5.66–5.99 | 4.36–4.59 4.88–5.07 5.38–5.65 6.00–6.29 | 1028 1029 1030 1031 | 36.7–38.8 41.9–44.3 | 38.9-41.8 44.4-45.0 | 1047 1048 |
| 6.30-6.67 7.01-7.42 7.83-8.29 8.80-9.24 | 6.68-7.00 7.43-7.82 8.30-8.79 9.25-9.67 | 1032 1033 1034 1035 | ▲Each of these numbers prefixed by "H" is the catalog number of a package containing one coil. Order as many packages as the number of coils needed. | | |
| 9.68-10.2 | 10.3-10.8 TLER-HAM | 1036 MER | WARNING — To provide continued protection against fire or shock hazard, the complete overload relay must be replaced if burnout of the heater coil occurs. | | |

